

产品中有害物质的名称及含量
China EEP Hazardous Substances Information

| 部件名称 Component Name | 有害物质 Hazardous Substances | | | | | |
|-------------------------------------|------------------------------|-----------|-----------|-----------------|---------------|-----------------|
| | 铅 (Pb) | 汞 (Hg) | 镉 (Cd) | 六价铬 (Cr(VI)) | 多溴联苯 (PBB) | 多溴二苯醚 (PBDE) |
| (显示器) Display | X | o | o | o | o | o |
| (电机组件) Electromechanical Assemblies | X | o | X | o | o | o |
| (机加工件) Machined Parts | X | o | o | o | o | o |
| (电路板) PCBA's | X | o | o | o | o | o |
| (电源供应器) Power Supply | X | o | o | o | o | o |
| Electromechanical relay (机电继电器) | o | o | X | o | o | o |

本表格依据SJ/T11364的规定编制 This table is compiled according to SJ/T 11364 standard.

O: 表示该有害物质在该部件所有均质材料中的含量均在GB/T26572规定的限量要求以下.
Indicates that the concentration of the hazardous substance in all homogeneous materials for the part is below the relevant threshold of the GB/T 26572 standard.

X: 表示该有害物质至少在该部件的某一均质材料中的含量超出GB/T26572规定的限量要.
Indicates that the concentration of the hazardous substance in at least one homogenous material of the part is above the relevant threshold of the GB/T 26572 standard.